

## Not to Scale

## **LEGEND**

Seepage

## NOTE

The thicknesses and elevations of these geologic units vary from place to place, and one or more units could be missing due to previous erosion.

Seattle Landslide Study Seattle Public Utilities Seattle, Washington

## IDEALIZED GEOLOGIC CONDITIONS TYPICAL SEATTLE HILLSIDE

July 1999

W-7992-01

SHANNON & WILSON, INC. Geotechnical and Environmental Consultants

FIG. 1-1